

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

CEDAR CITY AUTOMOTIVE REPAIR SHOP, CONCRETE
RETAINING WALL
820 North Main Street
Cedar City
Iron
Utah

HABS UT-139-E

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Steve Tregeagle, photographer, April 2009

- | | |
|------------|---|
| UT-139-E-1 | CONCRETE RETAINING WALL, DETAIL OF LOADING PLATFORM NEAR CENTER OF WALL, UPHILL SIDE VIEW TO SOUTHWEST. |
| UT-139-E-2 | CONCRETE RETAINING WALL, DETAIL OF LOADING PLATFORM NEAR CENTER OF WALL, UPHILL SIDE VIEW TO SOUTHWEST, WITH SCALE. |
| UT-139-E-3 | CONCRETE RETAINING WALL, DETAIL NEAR LOADING PLATFORM, VIEW TO NORTHEAST, BLM STORAGE SHED VISIBLE IN BACKGROUND. |
| UT-139-E-4 | CONCRETE RETAINING WALL, DETAIL NEAR LOADING PLATFORM, VIEW TO NORTHEAST, WITH SCALE, BLM STORAGE SHED VISIBLE IN BACKGROUND. |
| UT-139-E-5 | CONCRETE RETAINING WALL, DETAIL OF EXPANSION JOINT AND WEEP HOLE, VIEW TO EAST. |
| UT-139-E-6 | CONCRETE RETAINING WALL, DETAIL OF EXPANSION JOINT AND WEEP HOLE, VIEW TO EAST, WITH SCALE. |